



Port of Barbados:

Hydro-demolition of berthing dolphins and reinstatement with dry spray gunite. Additional repairs to harbour wall in shallow draft marina.



Main Contractor:
Delcan (Canada)

Sub contractor:
Lagan Construction Ltd (N.I.)




La Collette Power station -

Jersey - Channel Islands.

Dry sprayed concrete repairs to columns and beams at the top of the chimney stack.



Main Contractor;
Makers UK Ltd



'An Culu' Castle -

Kenmare - Co. Kerry - Eire

Construction of cavern over the swimming pool and jacuzzi area in the basement of the castle. Return visit to construct waterfall rock formation to feed the moat surrounding the castle (as you do !!).

Client; Private (as you would expect)



Tessenderlo -
Limburgh - Belgium

Re-lining chimney with refractory materials.

